



P1726 · Jaguar

Engine Overspeed

P1726 on a Jaguar indicates the engine control module (ECM) has detected an engine speed exceeding the manufacturer's safe limit, typically due to a mechanical over-rev or a faulty signal from the crankshaft position sensor. The ECM stores this code when the calculated engine speed (RPM) surpasses the threshold for a calibrated time, often triggering a limp mode to protect the powertrain.

SYSTEM	CODE TYPE	SEVERITY	FIX DIFFICULTY	AREA
Powertrain	Jaguar specific	Medium	Intermediate	Transmission

Symptoms you may notice

- Engine warning light illuminated, often with no other noticeable symptoms
- Engine enters limp mode, limiting RPM and power
- Rough running or misfire at high RPM
- Transmission may refuse to upshift or downshift abruptly
- Stalling or difficulty restarting after the event
- Audible over-revving or missed shift (in manual transmission cars)

Common causes, most likely first

- 1 Faulty crankshaft position sensor or damaged reluctor ring
- 2 Wiring harness damage or poor connection at the crankshaft sensor
- 3 Mechanical over-rev caused by missed gear or aggressive downshift
- 4 Engine control module (ECM) software glitch or internal fault
- 5 Aftermarket tuning or remapping that raised the rev limiter
- 6 Contaminated or failing camshaft position sensor (less common)

How to diagnose and fix it

- 1 Scan all modules for stored and pending codes, and record freeze-frame data to confirm the RPM at fault
- 2 Visually inspect the crankshaft position sensor and its wiring for damage, corrosion, or loose connectors
- 3 Check the reluctor ring on the crankshaft pulley for cracks, missing teeth, or debris
- 4 Perform a resistance and signal test on the crankshaft sensor using a multimeter or oscilloscope
- 5 Verify the ECM software is up to date and check for any aftermarket tuning that may have altered the rev limit
- 6 If the sensor and wiring are good, perform a road test with live data to monitor RPM signal consistency
- 7 Replace the crankshaft position sensor if faulty, clear the code, and re-test; if the code persists, diagnose the ECM



Over-Rev Code Often Misdiagnosed

- A dirty or damaged crankshaft reluctor ring can produce erratic RPM signals that the ECM interprets as an overspeed event, even when the engine never actually exceeded the limit.
- On some Jaguar models, a low battery or voltage spike during cranking can cause a false P1726 by disrupting the ECM's self-test; always check battery health before replacing sensors.
- Aftermarket alarm or remote start systems that tap into the crankshaft sensor wiring can introduce interference and trigger this code intermittently.
- A sticking throttle body or faulty accelerator pedal sensor can cause unintended acceleration and a genuine overspeed, so these should be ruled out before condemning the ECM.
- The code may be stored alongside transmission codes (e.g., P0729) if the overspeed was caused by a missed shift, so always check all modules for related faults.

Can I keep driving with P1726?

If the engine warning light is on but the car drives normally, you can drive cautiously to a workshop, avoiding hard acceleration and high RPM. If the engine is in limp mode or running poorly, stop driving and have the vehicle towed to prevent further damage.

Tools that help

- OBD-II scanner with live data and freeze-frame capability
- Digital multimeter
- Oscilloscope (for signal analysis)
- Basic hand tools (socket set, screwdrivers)
- Feeler gauge (for sensor gap check)
- Jaguar-specific diagnostic software (e.g., SDD)

Reading P1726

P	Powertrain: engine, transmission and emissions.
1	Manufacturer-specific code (Jaguar): its meaning depends on the make.
7	Transmission.
26	The exact fault within that area.

Often seen with

P1235 Fuel Pump Control Circuit · **P1235** VSV 1/2/3 Circuit Range Performance · **P1235** Fuel Pump Control Out of Range · **P0335** Crankshaft Position Sensor A Circuit Malfunction · **P0336** Crankshaft Position Sensor A Circuit Range/Performance · **P0700** Transmission Control System Malfunction · **P0729** Gear 6 Incorrect Ratio



See it working

Watch the animated explainer [How a Radiator Fan Relay Circuit Works](#) on Auto Veteran to see the parts involved moving.

Full guide, related articles and animations: <https://www.autoveteran.tech/dtc-codes/jaguar-p1726/>

